

# Speed Enforcement Evaluator

**Location:**  
**Rockview Avenue**

**GPS:**  
 0' 0.0000 South  
 0' 0.0000 East

**Closest Cross Street:**  
 Mercer Ave.


**Analysis Dates:**  
 Tuesday, June 15, 2021  
 Tuesday, June 22, 2021

**Equipment Used:**  
 Radar Recorder


**Installed By:**  
 Sgt. Dennis P. Kardos

**Requested By:**  
 Resident of 76 Rockview Avenue

Total Percentage of Enforceable Violations



0% 10%  
**Posted Speed Limit:** 25 MPH  
**Percentage Above Limit:** 0.5%  
**Enforcement Rating:** **LOW**



Combined

1-5	6-10	11-15	16-20	21-25	26-30	31-35	36-40	41-45	46-50	51-55	56-60	61-65	>65
0	44	409	2027	3713	2367	455	36	8	1	0	0	0	0

85 percentile = 27

Lane1

1-5	6-10	11-15	16-20	21-25	26-30	31-35	36-40	41-45	46-50	51-55	56-60	61-65	>65
0	13	194	1058	2097	1481	259	19	2	1	0	0	0	0

85 percentile = 27

Lane2

1-5	6-10	11-15	16-20	21-25	26-30	31-35	36-40	41-45	46-50	51-55	56-60	61-65	>65
0	31	215	969	1616	886	196	17	6	0	0	0	0	0

85 percentile = 27